

# State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

# INSPECTION REPORT

Michael O. Leavitt Governor

Kathleen Clarke Executive Director Lowell P. Braxton Division Director 1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

Partial: Co	omplete: XXX	Exploration:	
Inspection Date	e & Time: 09/2	29/00 / 10:00AM	-2:20PM
Date of Last In			

Mine Name: Wellington Preparation Plant County: Carbon Permit Number:
Permittee and/or Operator's Name: Nevada Electric Investment Company (NEICO)
Business Address: c/o Mt. Nebo Scientific, P.O. Box 337, Springville, Utah 84663
Type of Mining Activity: Underground Surface Prep. Plant XXX Other
Company Official(s): Patrick Collins
State Official(s): Stephen J. Demczak Federal Official(s): None
Weather Conditions: Warm 70's
Existing Acreage: Permitted 1573.5 Disturbed 392 Regraded 1.5 Seeded 1.5
Status: Exploration Active XXX Inactive Temporary Cessation Bond Forfeiture
Reclamation (Phase I Phase II Final Bond Release Liability Year)

# REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		<b>EVALUATE</b>	<u>N/A</u>	<u>COMMENTS</u>	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]	$\Box$	[X]	П
2.	SIGNS AND MARKERS	[X]	$\Box$	[X]	$\Box$
3.	TOPSOIL	[X]	$\Box$	[X]	$\Box$
4.	HYDROLOGIC BALANCE:				
	a. DIVERSIONS	[X]	$\Box$	[X]	$\Box$
	b. SEDIMENT PONDS AND IMPOUNDMENTS	[X]	$\Box$	[X]	
	c. OTHER SEDIMENT CONTROL MEASURES	[X]	$\Box$	[X]	$\Box$
	d. WATER MONITORING	[X]	$\Box$	[X]	
	e. EFFLUENT LIMITATIONS	· [X]	$\Box$	[X]	П
5.	EXPLOSIVES	$\Box$	[X]	$\Box$	$\Box$
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	П	[X]	$\Box$	$\Box$
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[X]	$\Box$	[X]	$\Box$
8.	NONCOAL WASTE	[X]			
9.	PROTECTION OF FISH, WILDLIFE AND RELATED	[X]		$\Box$	$\Box$
	ENVIRONMENTAL ISSUES				
10.	SLIDES AND OTHER DAMAGE	[X]	$\Box$	$\Box$	$\Box$
11.	CONTEMPORANEOUS RECLAMATION	[X]	$\Box$	· []	
12.	BACKFILLING AND GRADING	[X]		$\Box$	$\Box$
13.	REVEGETATION	[X]	$\Box$	$\Box$	$\Box$
14.	SUBSIDENCE CONTROL		[X]	$\Box$	$\Box$
15.	CESSATION OF OPERATIONS	П	$\Box$	П	$\Box$
16.	ROADS:				
	a. CONSTRUCTION/MAINTENANCE/SURFACING	[X]	$\Box$	Ш	$\Box$
	b. DRAINAGE CONTROLS	[X]	$\Box$	$\Box$	$\Box$
17.	OTHER TRANSPORTATION FACILITIES	[X]			$\Box$
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]		[X]	$\Box$
19.	AVS CHECK (4th Quarter- April, May, June)	[X]		П	$\Box$
	AIR QUALITY PERMIT	[X]		[X]	$\Box$
	BONDING & INSURANCE	[X]		[X]	$\Box$
			-		

#### INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: ACT/007/012

DATE OF INSPECTION: 09/29/2000

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

# 1. PERMIT

No new amendments have been sent to the Division by the permittee.

A photo was taken of Mr. Siaperas' field and house from the Wellington Prep. Plant by the Siaperas ditch as shown on Photo #1: Mr. Siaperas' field and house.

# 2. SIGNS AND MARKERS

The perimeter markers were spot-checked and are located around the perimeter of the disturbed area.

# 3. TOPSOIL

The topsoil piles were inspected with no signs of wind or water erosion. These piles are protected by berms.

# 4A. DIVERSIONS

The diversions were spot-checked and were found to comply with the requirements of the Mining and Reclamation Plan and the R645 Coal Rules. The undisturbed diversion on the west side has been cleaned out as shown on Photo #2: Clean out of undisturbed diversion

# 4B. SEDIMENT PONDS

The sediment ponds were not discharging during the inspection and are not likely to discharge in the near future. These ponds did contain a little or no water. There were no signs of any hazardous conditions during the inspection. The sediment ponds were inspected on June 2, 2000 for second quarter. The inspections are P.E. certified.

Enclosed are photos showing the upper and lower slurry ponds. Photo #3: Lower Slurry Pond and Photo #4: Upper Slurry Pond.

# 4C. OTHER SEDIMENT CONTROL MEASURES

The Wellington Loadout facilities uses straw bales and silt fences as its alternate sediment control measures. These areas were spot-inspected and complied with the R645 Coal Rules. A silt fence along the Siaperas needed maintenance as shown on Photo # 5: Silt fence needing repair (before). The permittee repaired the silt fence during the inspection as shown on Photo #6: Silt fence repaired (after).

# 4D. WATER MONITORING

Water monitoring for second quarter was done and was submitted on June 4, 2000. This report was electronically submitted. Surface and ground water was spot checked with no problems noted.

#### INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: ACT/007/012

DATE OF INSPECTION: 09/29/2000

#### 4E. EFFLUENT LIMITATIONS

No UPDES samples were taken for second quarter. There was no discharge from the sediment ponds.

# 5. EXPLOSIVES

No explosives boxes are on the property.

#### 7. REFUSE PILES

Refuse pile was inspected with no hazardous conditions being noticed. The slurry ponds were inspected weekly. All refuse piles have been inspected for second quarter and are P.E. certified.

# 8. NON-COAL WASTE

The area was clear of non-coal waste material.

# 20. AIR QUALITY

The air quality permit is being complied with. There are two Air Quality permits for Wellington Prep. Plant. Covol has a separate permit (DAQE-1014-97) and NEICO has a permit (DAQE-997-92). There was no activity on either permit.

# 21. BONDING AND INSURANCE

The permit area is 1573.5 acreage and the disturbed area is 392 acres. Exhibit "A" states that the bonded area equals the permit area. The bonding is set at \$4,904,000.

The insurance acord form meets the requirements of the R645 Coal Rules. This policy will expire on October 8, 2000. The insurer is Claremdon Insurance Co.

Inspector's Signature:

Stephen J. Demczak

Date: October 3, 2000

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

sd cc:

James Fulton, OSM

Patrick Collins, Mt. Nebo for NEICO

Price Field office

O:\007012.WEL\Compliance\2000\C 0929 .wpd

(Photograph Attachment)

DATE OF INSPECTION: 9/29/2000

(PHOTOGRAPHS)




Photo #1: Mr. Siaperas' field and house



Photo #2: Clean out of undisturbed diversion

DATE OF INSPECTION: 9/29/2000




Photo #3: Lower Slurry Pond



Photo #4: Upper Slurry Pond

(Photograph Attachment)

DATE OF INSPECTION: 9/29/2000



Photo # 5: Silt fence needing repair (before)




Photo #6: Silt fence repaired (after)